



Valorem Technology Inc.
 2650 Walnut Ave. Suite H
 Tustin, CA 92780
 (714)200-8694
 support@valoremtech.com

Invoice

Date	Invoice No.
03/04/2014	1097
Due Date	
	03/04/2014

Bill To

Tustin Ranch Golf Club
 12442 Tustin Ranch Road
 Tustin, CA 92780
 United States of America

Amount Due	Enclosed
\$217.83	

Please detach top portion and return with your payment.

Date	Service	Activity	Quantity	Rate	Amount
03/03/2014	Telecom Support	Task/Ticket: Voicemail trouble T20140303.0001 Summary Notes: Checked the Call Pilot voicemail, the system is not responding and does not reboot. The power supply may have failed and should be replaced. Waiting on vendor response for replacement part.	0.5	100.00	50.00
03/04/2014	Telecom Support	Task/Ticket: Voicemail trouble T20140303.0001 Summary Notes: Replaced the power supply and checked the programming of the voicemail. The voicemail is working and no programming is required.	0.75	100.00	75.00
03/04/2014	Nortel Parts	Nortel Call Pilot - Power Supply T20140303.0001 Cost Description: Power supply for Nortel Call Pilot 100/150	1	79.00	79.00T
03/04/2014	Shipping	Shipping charges, overnight, special handling, expedite fees.	1	7.50	7.50

Thank you for selecting Valorem Technology, Inc. for you IT needs.

SubTotal	\$211.50
Tax (8%)	\$6.33
Total	\$217.83